

FIG.1




FIG.2




FIG.3






FIG. 4








FIG.7






FIG.8



8








FIG.12





830




FIG.15




FIG.16

У ₄	y ₃	y ₂
y ₅	у ₀	у ₁
y ₆	У ₇	у ₈

FIG.17A




FIG.17B

R ₀ 1	y ₄	у ₃	y ₂
	y ₅	y ₀	У1
R _e ²	У <u>б</u>	У 7	У ₈

⊖=0° n=1

FIG.18A




FIG.18B


У ₄	y ₃	У2
У ₅	y ₀	У1
У ₆	y ₇	<u>y</u> 8
R ₀ 1		R _e ²
е	90° n=	: 3


FIG.18C

У ₄	у ₃	y ₂	R
У <u>5</u>	у ₀	У1	
У ₆	У7	y ₈	
R _e ²			

⊖=135° n=4

FIG.18D








FIG.21

X 4	Х 3	X 2
X 5	х _о	Х ₁
Х _б	X 7	Х8

FIG.22








FIG.23









President Byoung-Ho Cho

Mobile:+82-11-505-2356

Yeon-woo Bldg3F,416-8, Chimsan-Dong, Buk-Gu, Daegu, Korea (702-0 Tel:+82-53-217-1000 Fax:+82-53-217-1070 Union Center 1403, 837-11

Width/Length

Recognize

(Shoot)

FIG.26A

President Byoung-Ho Cho

Mobile:+82-11-505-2356

Yeon-woo Bidg3F,416-8, Chimsan-Dong, Buk-Gu, Daegu, Korea (702-0 Tel:+82-53-217-1000 Fax:+82-53-217-1070 Union Center 1403, 837-11

FIG.26B




FIG.26C SAVE ON! Pic. name:_P00001 2002/07/18 Save Recognize Cancel

FIG.26D




FIG.26E




FIG.27A




FIG.27B




FIG.28A




FIG.28B




FIG.28C




FIG.28D




FIG.29A




FIG.29B




FIG.30




FIG.31




FIG.32




FIG.33

240

ERROR CORRECTION PROCESS START

FIG.34A




FIG.34B




FIG.34C




FIG.34D